

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

KW1498
NNW
> 1
1.884 mi.
9948 ft.

MANHOLE #6892
IFO 2061 86TH ST
BROOKLYN, NY

NY Spills S104881223
N/A

Site 3 of 4 in cluster KW

Relative:
Higher

Actual:
25 ft.

SPILLS:

Name: MANHOLE #6892
Address: IFO 2061 86TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0010607 / 2001-04-19
Facility ID: 0010607
Facility Type: ER
DER Facility ID: 170117

Site ID: 204641
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2000-12-21
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2000-12-21
CID: 390
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-12-21
Spill Record Last Update: 2001-06-19
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller Company: 999
Contact Name: BILL MURPHY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks:

O'CONNELL DEC INSPECTOR'S NOTES CON ED E2MIS REPORT 12-21-00 7gals.
of unknown oil on approx. 800gals. of water in MH6892 Can't tell if
there is a sump due to amount of water. Liquid sample taken. Lab Seq#
00-11918 <1ppm 12-20-01 Structure cleaned from top due to rain water
pouring into hole, double washed, no sump in hole, removed tag#54348"
"7 gals unk oil on 800 gals of water - sample taken clean up pending
lab results con ed #134849"

All Materials:

Site ID: 204641
Operable Unit ID: 832635
Operable Unit: 01
Material ID: 544501
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 7.00
Units: G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Recovered: .00
Oxygenate: Not reported